MIDWAY MFG. CO.
280 ZZZAP
GAME LOGIC
P.C. 0610-00907A

NOTE REVISIONS:

A) FIRST 70 UNITS DID NOT HAVE INVERTER (E1 PINS 5-6) AND WENT TO PIN 12 INSTEAD OF PIN 15 F1.
B) AT 325 UNITS THE FOLLOWING CHANGES WERE INCORPORATED:
C) CAP BETWEEN C2 PIN 7 AND GRND. WAS CHANGED FROM .047MF. TO .082MF.
D) CAP BETWEEN C1 PIN 7 AND GRND. WAS CHANGED FROM .0047MF. TO .0082MF.
E) 2.2K RESISTOR AT G4 PIN 2 WAS 6.8K.
F) 12K RESISTOR IN SERIES WITH 10MF CAP AND J5 PIN 8 WAS 4.3K.
G) 500MF CAP AT H2 PIN 8 WAS 100MF.
H) MAKE CONNECTION---BETWEEN 20V RETURN AND LOGIC GRND.